
Unassigning A Dual Channel Receiver Channel

One of the channels of the Dual Channel Receiver has been assigned to 2 or more zones. This will stop the Dual Channel Receiver working properly and may mean rooms heat unexpectedly or do not heat up at all.



Select the Dual Channel Receiver which has been assigned incorrectly.

The number for the Dual Channel Receiver may be on the side of the device.

The Dual Channel Receiver channel is assigned to the following rooms. Please select the one room you wish to control with this channel.

The correct zone to be controlled may be on the label inside the door of the Dual Channel Receiver.

The Genius Hub will now unassign the Dual Channel Receiver channel from all zones.

The success of the action will be displayed on screen.

The Genius Hub will now assign the Dual Channel Receiver Channel to the correct zone.

The success of the action will be displayed on screen.